



<p>x 46</p> <p>(a)</p>	<p>x 12</p> <p>(b)</p>	<p>x 1 (562 mm)</p> <p>(c)</p>
<p>x 20</p> <p>(d)</p>	<p>x 8</p> <p>(e)</p>	<p>x 5 (kpl.)</p> <p>(f)</p>
<p>x 4</p> <p>(g)</p>	<p>x 20 (3,5x30)</p> <p>(h)</p>	<p>x 60 (3,5x16)</p> <p>(i)</p>
<p>x 110</p> <p>(j)</p>	<p>x 1</p> <p>(k)</p>	<p>x 1</p> <p>(l)</p>



1 - FAZY MONTAŻU

A - OZNACZENIE ELEMENTÓW

a - OZNACZENIE AKCESORIÓW

